

BSMI brings Digital Set-Top Box Inspection into force from now on

Jan. 2, 2008

Per BSMI's (Bureau of Standards, Metrology & Inspection) Public Notices, "Legal Inspection of Video Tuners having Digital Terrestrial Television Reception Capability" comes into force since January 1st, 2008. All devices with terrestrial television reception capability are required to be inspected from now on.

Covered products, inspection standards and inspection scheme as below:

| | |
|-------------------------|--|
| Product | Video tuners having terrestrial television reception capability (those for vehicle and computer used only are exclusive) |
| HS/CCCN Codes | 8528.12.10.00-1 |
| Inspection Standards | EMC: CNS 13439 (2004) ; manufacturers may choose to adopt CNS 13438 (2006) for multi-media products |
| | SAFETY: CNS 14408 (2004) ; manufacturers may choose to adopt CNS 14336 (2005) for multi-media products |
| | Technical Specification for Digital Terrestrial Television Receivers CNS 14972 and CNS 14409 (EMS) CNS 14676-4 (EFT) CNS 14676-5 (Surge) |
| Inspection scheme | RPC (Registration of Product Certification) scheme (Modules II + III) |

Note: Those without terrestrial television reception capability and with cable television reception function only are exclusive. But those with two functions above are required to be inspected.

For further information please contact us at sales@adt.com.tw

For additional information on ADT, please visit www.adt.com.tw